

West Horsley Parish Council List of Roads & Pavement Repairs March 2023

HIGH PRIORITY – These pose a clear safety risk to residents and require urgent attention:

<u>Issue</u>	<u>Location</u>	<u>WHPC Notes</u>	<u>SCC Reference and back ground info</u>
Speed limit	Bell & Colvill roundabout to St Mary's Church	Reduce to 40 mph. Agreed. When being delivered? CY has chased SCC 27/6/2022	Due for delivery March 23 but this has been 'imminent' since March 22 and remains a safety priority for West Horsley. Confirmed for delivery before end March 23.
Pavement	From West Horsley Village Hall, The Street, to Bell & Colvill garage/A246	Poor state of pavements – uneven, broken, impassable for pushchairs/wheelchairs.	With the increase in heavy traffic associated with local developments, this stretch of pavement along the main highway through West Horsley is extremely hazardous and presents a clear danger for pedestrians.
Pavement/Hedges	From West Horsley Village Hall, The Street, to Bell & Colvill garage/A246	As above – hedges in urgent need of attention/cut back to widen pathway	Linked to above pavement issue. Outstanding since 2022 when no works were carried out as no budget. Needs addressing in 2023.
Roads/flooding	The Street, by railway bridge.	<p>Ref: 2415227 reported 16/11 after severe flooding forced resident to rescue horses for neighbouring field. Dangerous potholes now forming on this section of the road.</p> <p>Surrey Highways scheduled to jet out drains from road to stream on 06/12. No improvements noted since. Dep Clerk has escalated via Surrey Highways email on 29/12.</p> <p>18/01/23 – Cllr Colbourne-Baber and Buosi to approach resident at Winterfold.</p>	<p>SCC Ref: 2415227</p> <p>Last reported 16/11/22 after severe flooding.</p> <p>A long term issue that needs thorough investigation to resolve.</p> <p>Excessive flooding also leading to dangerous potholes, sunken manhole covers.</p> <p>Flooding regularly results in road closures, hence HIGH PRIORITY FOR RESOLUTION.</p>
Roads/Flooding	Long Reach (Ockham end)	Major flooding at Ockham end of Long Reach. Ockham PC have engaged Councillor Cross and Surrey Highways. Flooding issues potentially worse since extensive tree felling at A3/M25 works. WHPC and Ockham PC to work together to push for resolution.	SCC Ref: 2448893 – reported by Councillor Cross on 03/01/2023.

MEDIUM PRIORITY – Issues that have had an initial SCC assessment but remain of concern to WHPC or issues that affect secondary roads

<u>Issue</u>	<u>Location</u>	<u>WHPC Notes</u>	<u>SCC Reference and background info</u>
Roads/Sink holes	2 x sink holes reappearing outside West Horsley Village Hall, The Street, West Horsley KT24 6DD MAIN SPINE ROAD OF VILLAGE	Ref: Kevin Deanus – last communication 11/11. Full history shared with Matt Furniss. Thames Water and Surrey Highways monitoring situation but not considered worthy of repair as they stand.	West Horsley Parish Council would like it noted that there is a significant history at this location and a serious road injury occurred when the sink holes last collapsed. We would request that SCC conduct regular monitoring of the site.
Roads/Sink holes	Dips in Ockham Road North, Near Green Lane entrance. MAIN ROAD	Last communication 22/12 via Edward Scott (resident). Warning javascript:void(0); signs have been erected.	SCC Ref: 2398309. Considered not a danger in present state. However, West Horsley PC do not agree. With current speed limits any motor cyclist hitting this dip would be thrown off the road, close proximity to caravan site also makes it a danger to caravan users.
Drains	Ripley Lane from junction with The Street and down to railway bridge.	All drains completely blocked and adding to localised flooding. No evidence of cleaning for many years.	SCC Ref: 2311135 reported 20/07/2022. SCC Ref: 2474444 re-reported 18/01/23.
Drains	East Lane from no. 111 to junction with Ockham Road North.	All drains completely blocked. Need clearing. As per Ripley Lane.	SCC Ref: 2311089 reported 20/07/2022.
Pavement	East Lane near Northcote Road	Large tree stump has broken and pushed pavement up – impassable for pedestrians with buggies/prams or wheelchair users. (Photos attached). Pedestrians forced into the road.	SCC Ref: 2289929 reported 28/06/2022 Remedial works have been carried out but have not solved the issue. Pedestrians with pushchairs or wheelchairs CANNOT pass this area and are forced onto the road. Re-instated under SCC Ref:
Pavement/Road	Mount Pleasant from Cranmore Lane towards Overbrook.	Damaged surface needs to be repaired.	

		Some uncertainty as to responsibility/ownership as part adopted road, part not. WHPC TO INVESTIGATE.	
--	--	--	--

LOW PRIORITY – These are mainly residential roads.

<u>Issue</u>	<u>Location</u>	<u>WHPC Notes</u>	<u>SCC Reference and background info</u>
Roads/Pothole	Pothole on The Street by railway bridge.	Recorded on SCC portal. Followed with email from Dep Clerk to express urgency of matter.	SCC Ref: ?? Some works have taken place. TBC if closed.
Road	Silkmore Lane	Road surface broken away, large potholes. Caused during recent housing developments and heavy site traffic accessing this road.	SCC Ref: 2289920 – first reported 28/06/22.
Pavements/Verges	Woodside	Pavement surface disintegrated. Loose gravel and large potholes. Needs resurfacing. Verges need repair.	
Pavement/Road	Greta Bank	Road and pavement surface severely worn with potholes and loose kerbstones.	
Pavement	Top of Long Reach from The Street down to Woodside	Repair pavements.	
Road/Pavement	Entrance to Farleys Close off Long Reach	Damaged surfaces need repairing. (Photos attached)	SCC Ref: 2289936 first reported 28/06/2022

WORK IN PROGRESS – These are issues that are due to be completed/future funding has been secured but need monitoring until delivery.

<u>Issue</u>	<u>Location</u>	<u>WHPC Notes</u>	<u>SCC Reference and background info</u>
Road Markings	Raleigh School, Northcote Crescent. Investigating potential for double yellow lines to extend current zig zag	Reported to Duncan Knox, Road Safety & Sustainable School Travel Manager at Surrey CC (07581 619476) 09/03/22	Needs progressing.

	<p>'keep clear' around the bend opposite the green and bollards. School bus/bin lorry cannot turn this bend without mounting the kerb and green, meaning the bollards cannot be installed and traffic is continuing to park on the green causing a safety hazard and damage.</p>	<p>Site visit took place 03/11 (Cheryl Faure, Safer Travel Team and Soe Hein, Surrey Highways). A number of improvements suggested to reduce dangerous parking, congestion. Report forwarded to Highways. Dept Clerk has requested details re next steps and possible time frames for implementation. Email to Cllr Cross 19/01/23 re potential budgets for this.</p>	<p>It was identified that appropriate signage was needed in order to make the existing restriction markings enforceable.</p> <p>Is there funding available under the Road Safety budget?</p>
Footpath	<p>Footpath 91 from Cranmore Lane to A246/Cranmore School</p>	<p>Footpath collapsed, huge holes down to development. Extremely dangerous for all pedestrians. High level of children uses for access to Cranmore School and the Howard of Effingham school bus stop. Needs URGENT attention. ACTIONED BY CY.</p>	<p>Repairs to be made by developer at 20 The Street.</p> <p>Some works carried out. Needs monitoring until completion of development.</p>
Pavement	<p>Northcote Crescent and Northcote Close</p> <p>Surrey Highways Ref: 2289864 logged 28/06</p>	<p>Pavement surface entirely disintegrated in many places. Potholes and complete loss of road surface in numerous locations. See attached photographs and map for detail. This is an area with high pedestrian traffic – used by children and parents with buggies and prams for the school and a cul-de-sac of elderly residents (Northcote Close).</p>	<p>SCC Ref: 2289864 reported 28/06/2022.</p> <p>This has not been added to the project list for 23/24 funding.</p> <p>The footways/pathways form part of Project Horizon, for future funding.</p>
Pavement	<p>Northcote Road from East Lane to Northcote Crescent</p>	<p>Pavement surface disintegrating in many places. Sunken pavements leaving dangerously raised kerbstones – a serious trip hazard for pedestrians, many of which are children and elderly.</p>	<p>SCC Ref: 2289909 reported 28/06/2022.</p> <p>See above. This project has been put forward to be part of Project Horizon funding.</p>
Bridleway	<p>Cranmore Lane, Bridleway 482 From 'Little Wings' to Little Cranmore Lane</p>	<p>Ongoing since 2020 – poor state of surface making it impassable for pedestrians and horses. FOLLOWED UP BY CY 27/6. To actioned summer 22 by Countryside Access Team. Jan 23 – no works progressing. Dept Clerk emailed John Baker 23.01.23 for update</p>	<p>John Baker, Countryside Access Team – works on ditches complete and vegetation cut back.</p> <p>Works to improve the path surface will take place in Summer 23 once ground dries out.</p>